



1

Diagram 1: Preparing the mounting plate (II) and the base (I).

2

Diagram 2: Mounting the plate to the wall using screws and a screwdriver. Includes a warning: OFF (with lightning bolt icon).

3

Diagram 3: Wiring the base. Shows connection to a 12V source. Includes a detail of the terminal block with 'push' and 'L', 'N' labels. Includes a warning: =12 V.

4

Diagram 4: Attaching the lens (II) to the base (I).

5

Diagram 5: Inserting the QR111 G53 bulb (III) into the base (I). Shows the lens (II) and base (IV).

6

Diagram 6: Final assembly of the spot light. Includes a warning: ON (with lightning bolt icon).

